



The Quantum2 firmware update includes the following:

- Improved communication between the modules
- Flexibility to insert the cleaning card manually in the feeder module without using the hopper.

Fixing of the following bugs:

- YMCKOK + magnetic
- LCD message
- Ribbon synchronization
- Magnetic encoding
- Pcp command

A new command, Pctr;Value has been designed:

the Pctr command allows sending cards to the "Reject" tray (Pctr;all/Pctr;stop or Pctr;xx (xx is a number < 100))